

## Drainage Projects/Maintenance 10-1-2022

Panther Way by the Highschool, ditch heavily silted.

Before



After





Erosion rock (rip rap) added to wash out areas



Creek Crossing located at Castleman Creek

Before



After



Underground drainage pipe located on Yorktown, roughly 40% flow capacity recovered

Before:



After



Drain for City Hall at Hewitt Drive

Before



After



Devonshire Detention Channel

Before



After




## Curb repairs

Gruver



Aston



Omaha





City Hall Parking Lot

